

# Ergebnis Millipore-Test

## MILLIPORE TEST

To: Madison Gas & Electric / Pat Summit  
Subject: GST 32 Turbine Oil – Bottom Sample  
Millipore Test Patch: 1.2 and 8 Micron

1.2      8



**Dirty Fluid**

(20 ML Through a 1.2 and 8 Micron Patch. ISO Code: High Baseline)

**1 Pass With A 6021(Media-2) Filter**

(ISO Code: 18/17/15)

**5 Passes With A 6021(Media-2) Filter**

(ISO Code: 15/14/13 )

**10 Passes With A 6021(Media-2) Filter**

(ISO Code: 13/11/9 )